

## 4. HYDRAULIC SYSTEM

Trouble	Service	Remark
Bucket lacks lifting power. Bucket lifting speed is slow.	<ul style="list-style-type: none"><li>• Check the hydraulic oil level and add if necessary.</li><li>• Replace filter in hydraulic tank.</li></ul>	
Bubbles in oil.	<ul style="list-style-type: none"><li>• Replace with specified oil.</li><li>• Add oil if needed.</li></ul>	
Oil pressure is too low.	<ul style="list-style-type: none"><li>• Bleed air from oil line.</li><li>• Add oil and bleed air.</li></ul>	
Cylinder vibrates when operating.	<ul style="list-style-type: none"><li>• Add oil.</li></ul>	