

4. HYDRAULIC SYSTEM

Trouble	Service	Remark
Bucket lacks lifting power. Bucket lifting speed is slow.	<ul style="list-style-type: none">• Check the hydraulic oil level and add if necessary.• Replace filter in hydraulic tank.	
Bubbles in oil.	<ul style="list-style-type: none">• Replace with specified oil.• Add oil if needed.	
Oil pressure is too low.	<ul style="list-style-type: none">• Bleed air from oil line.• Add oil and bleed air.	
Cylinder vibrates when operating.	<ul style="list-style-type: none">• Add oil.	